INSTRUCTIONS

No. 75 OUTSOLE STITCHING MACHINE (FOR NO. 2 VICTOR, SEE NEXT PAGE)

Catalogue reference: 9/0/1

Safety	Wiring	Illustr	Fault Finding	Maintenance	Lubrication	Operating	Setting up	Controls	Installation	Technical Data
		ated Par	inding	ance	tion	ng	qu	S	ation	al Data
:	:	rts Lie	:	:		:	:		:	
		št		:		:	:	•	:	:
Safety		Illustrated Parts List	•					:	•	
end of book	Section 10	. Section	Section	. Section	Section	. Section	Section	Section	Section	Section
11	10	9	00	7	6	U	4	w	2	1

The Company can accept no resposibility for malfunction if unapproved accessories or spares are used. WH&B MACHINES are designed to operate with the accessories supplied as initial equipment.

Our policy being one of continuing development and improvement, we reserve the right to alter specifications without notice.

NO. 2 VICTOR OUTSOLE STITCHING MACHINE

This book refers to the current model 75 Outsole Stitching Machine.

The only differences between this and the No. 2 Victor, apart from the shape of the column

ON/OFF switch and uses a different Indicator Lamp. The electrical control box (see Plate 1): This is a different type which does not have an

one-piece plastic cover shown in the book. The centre section opens by simply swinging it The motor starter is positioned on the left hand side of the column instead of the front. up and back. The side sections must be lifted slightly (with a hand at back and front The head cover: This consists of three hinged sections of cast aluminium instead of the

simultaneously) and then swung aside. The sight-feed lubricator on the head. This has an adjustable flow-valve, controlled by a small brass layer on the top. With the lever vertical, the oil flows; turn it down to the horizontal position to stop. Immediately below the lever is a knurled sleeve, with a then slowly sorew the sleeve up until it contacts the end of the lever and starts to lift it. away from the sleeve and screw the sleeve down. Turn the lever up to the "on" position, knurled locknut below it, which controls the rate of flow. To adjust, slacken the locknut

falls every fifteen seconds or so. Lock the adjustment by holding the sleeve still and watch through the window in the stem of the lubricator and adjust the sleeve so that a drip three-quarters full of oil. tightening the locknut up to it. The lubricator should be kept between a quarter and

TECHNICAL DATA

1 9	7	00	cord	Welt Thread. cord	
6	6 0	7	cord	Shuttle Thread, cord	
47	45	43	size	Needle,	
				read sizes:	Needle, Awl and Thread sizes:
Use only Left (Z) Twist Linen Thread.	(Z) T	y Left	Use onl		Thread:
5/8 in. (15.8 mm)	mm)	(15.8	5/8 in.	ness:	Maximum work thickness:
Infinitely variable, from 4 to 10 per inch (6.3 m	riable	ely va	Infinit		Stitch length:
Infinitely variable, up to 300 stitches/minute.	riable	ely va	Infinit		Stitching Speed:
Clockwise, viewed from pulley end.	ewed f	se, vi	Clockwi		Motor rotation:
		p.m.	1420 г.р.т.	eed (50Hz.):	Motor Full Load Speed (50Hz.):
0.55 kw.	0.	p.	0.75 h.p.		Motor output:
			60 w.	nt, loading:	Wax pot Heat Element, loading:
			75 w.	nt, loading:	Shuttle Heat Element, loading:
227 kg.	2:		500 lb.		Weight:
36 mm	686		27 ins.		Depth:
36 mm	686		27 ins.		Width:
22 mm	1422		56 ins.		Height:

(6.3 mm to 2.5 mm)

Wax (welt thread):

" (shuttle thread):

Bostik Liquid Stitching Wax.

BU Stitching & Sewing Wax (Golden or Brown as preferred).

INSTALLATION

Electrical connection to the Motor Starter should be made through an isolator and fuse of not less than 15 amps, capacity (1 ph.) or 10 amps, (3 ph.), positioned on or near the machine. The machine must be earthed. The machine must stand firmly and level, using packing under the corners if necessary. of not less than 5 amps. capacity. The heating circuit connection should be made through a normal earthed switch/plug outlet, preferably fused,

Wiring colour code: Earth Green/Yellow Live Brown

Neutral (1 ph) Blue

ELECTRICAL CONNECTIONS MUST BE MADE ONLY BY A QUALIFIED ELECTRICIAN.

Direction of rotation: The motor runs in a clockwise direction, viewed from the pulley end.

N

THE CONTROLS

- 1. Motor ON/OFF Switch.
- Shuttle & Wax Pot Heaters ON/OFF Switch.
- Shuttle heat Simmerstat.

=

Indicator Lamp.

- Wax Pot Heat Simmerstat.
- Stitch length Lever: Infinitely variable;
 Up for short stitch;
 Down for long stitch.
- Edge Gauge Lever: Infinitely variable; moves in opposite direction to Gauge.
- Presser Foot Raising Handle Push back to raise Presser Foot.
- Handwheel turns anti-clockwise.
- Bobbin Winder turns anti-clockwise.

10.

- Bobbin Winder operating Rod-Push in to start; Pull out to stop.
- Wax Stripper, hard wax pot.
 Dry thread tension.
- Clutch Treadle. Increase pressure to increase speed.

12. 13.

- 15. Wax Stripper, liquid wax pot.
- 16. Thread Holder.

Needle and Awl. These must be of the same size, in good condition, and fully home in their clamps Threading of Machine. The correct thread to use is WH&B Green Label (left twist). See table, Sec.1, "Technical Data". The course of the thread through the machine must be as shown in the diagram, Figs. 2 and 3. It is most important that the thread passes correctly through the Thread

To thread the machine for the first time

Measure (Fig. 1) otherwise breakage will occur.

through the top hole in the Bracket and over the Head Tie Rod (1, Fig.1). up, pass it through the lower hole in the thread Bracket on top of the Column, (from the inside), then back cop (small end uppermost) on the Thread Shelf inside the Column, at the back. Bring the end of the thread Take the cop of shuttle throad and untie the end which is tied round the outside of the cop. Stand the

Turn the machine so that the Thread Lock Cam Lever (2, Fig.1) is down, separating the Thread Lock Pins (3) - 12 ins (300mm) or more. and (4). Pass the thread between the Lock Pins from the back, under the lower Pin, and draw up a good length

Turn the machine until the Awl is fully to the left; in this position the thread hole (5, Fig.1) is aligned laterally with the holes in the Fresser Foot Holder (6) and the Thread Lock Cam Lever (2) is up.

with the hole (5), when the threader can be pushed right through, to pass under the Hook(7) and between the Foot Holder (6). Raise the Presser Foot by means of the Raising Handle to align the holes (6) vertically Take the threader supplied in the Kit and pass it through the thread hole (5) until it touches the Presser

Engage the thread in the hook of the threader (leaving sufficient slack to pass through the machine) and taking the weight of the Presser Foot Springs on the Raising Handle, draw the thread out through the hole (5).


under the Guide Screws (9, Fig. 2) if the Thread Guide Bracket (10), which is retained by the Binding Screw (11), From here, the thread takes the course shown in Figs. 2 and 3. is removed from the wax pot. It will be found easiest to engage the thread

stout cardboard core of the cop, which prevents the thread from being run right out. The beginning of the and under the $\operatorname{Hook}(7)$, as this is the thread measure which regulates the amount drawn out according to the should rarely be any need to re-thread the machine subsequently, as the end of the thread is tied to the cop is simply tied securely to the end of the old one and pulled through. It is most important that the thread passes correctly through the holes in the Presser Foot Holder (6)

thickness of the work.

Drg. No: RS/VSM/2

.Pla. 3



Removal and Replacement of Bobbin (Fig. 4)

Turn the machine to the starting position (see "Operating", Section 5).

P1.5). The Shuttle (VSM 80+, P1.12) can now be lifted out. Pull forward the Shuttle Bearing Lock Lever (VSM 141, Pl.5) and lift open the Shuttle Bearing Cap (VSM 13W,

as this would probably break the hardened point. CAUTION: If the machine is at working temerature, the Shuttle will be very hot. Be careful not to drop it,

again using the butt of a needle, through the hole provided in the back of the Shuttle for this purpose. could damage the hook). Rotate the Latch so that the hook lies across the end of the Bobbin Post and release Post in which it lies. (Do not attempt to do this by lifting the hook with a knife or screwdriver, as this back of the Shuttle, so that the hook of the Latch is lifted out of the small recess in the end of the Bobbin Take a spare needle and, with its butt end, press in the spring-loaded Bobbin Larch (VSM 21E, P1.12) from the it. The Bobbin can now be tipped out of the Shuttle. If it does not come out readily it can be pushed out,

Place the Shuttle on the Work Tray, with its point towards the right, and apply a few drops of oil to its

ection as the shuttle point. The Bobbin must be the correct way round in the Shuttle, i.e., the thread must run off it in the same dir-

first push the point of a needle through the Shuttle under the Tension Ball and use its barb to draw the thread in the centre and through this to emerge from the Bobbin Post on the other side, (see Fig.4). To do this, The thread then passes under the spring-loaded Tension Ball, across the back of the Shuttle to the small hole the centre hole, leaving a loose end approximately 3" (76mm) in length. is not trapped under the Bobbin, then turn the Latch until it drops into its recess. Pass the thread through through (Fig.4a), then insert the Bobbin in the Shuttle. Pull out a little of the thread to ensure that it

suring that the Lever returns to its backward position. If it does not, this indicates that the Shuttle is Replace the Shuttle and close the Bearing Cap, pulling the Lock Lever (VSM 141) forward to do this and ennot properly in position. The trailing end of thread protrudes from the front, between the Shuttle and the

the thread guide screws. the wax pot. Shaking is not sufficient. Do not over-fill the liquid wax pot - use just sufficient to cover preferred) on the Bobbin Thread. Liquid wax must be stirred thoroughly every time before pouring into Use only BOSTIK LIQUID STITCHING WAX on the welt thread and B.U. STITCHING & SEWING WAX (colour as

turn the Simmerstat (5) to "Full". It is easiest to thread the Hard Wax Pot before filling it with wax. Switch on the heater switch (2) and

Lift off the Wax Pot Cover, pull out the Pin (VSH 26D, Pl.7) and lift out the Thread Guide, (VSH 201, Pl.7).

ers. Hold the thread across the top of the Wax Pot and push it down with the Thread Guide, so that it lies in the groove under the lower end of the Guide, and replace the Pin (VSM 26D). Pull the thread into the end of the Stripper, between the two rubbers. pass it through the eye on the side of the Wax Pot and over the Dry Thread Tension (13) between the two wash-Place the cop of thread on the Thread Shelf, small end uppermost, until the thread from round the cop and

wise it may boil over. Wait until the first few pieces have melted, then add a little more and so on until Break up some wax into small pieces and place them in the Wax Pot. Do not put very much in at first, otherthe Pot is about half full. Do not over-fill. Replace the Cover.

Unscrew the Clamp Nut (VSM 63, Pl.4), place the empty bobbin on the spindle and replace the Clamp Nut. Switch on the motor.

Pull the thread up behind the bobbin and over it, taking three or four turns round the bobbin centre and

Start the Winder by pushing in the Operating Rod (11). Stop after a little thread has been wound on (by cutting the loose end off close to the centre. the thread well but not so much that it is squeezed out between the turns of thread. Regulate by tightening pulling out the Operating Rod) and check the amount of wax on the thread. There should be sufficient to cover

Continue winding and stop just before the bobbin is full. (An over-filled bobbin will not enter into the or slackening the two screws in the Stripper Plate.

It may be necessary to guide the thread whilst winding with a screwdriver blade or similar to prevent it piling Shuttle).

up at one side. The Shuttle heat must be regulated by the Simmerstat so that the thread runs freely. This

Shuttle heat. Welt Thread. Shuttle must be kept well oiled. with wax and must be cleaned periodically. It helps to oil them liberally at the end of the day's work, to This must run freely through the machine when pulled by hand. If it does not, check that the threading is correct, and that the Thread Rolls revolve freely. These tend to become clogged usually means setting on "Full" all the time whilst actually operating. The Bobbin and

prevent wax from hardening on them overnight.

Removal and Replacement of the Needle.

Switch off the machine.

needle can now be withdrawn from the Clamp and Needle Guide. a turn, taking care that the stem of the wrench does not bear against the Spreader Point and displace it. The square socket wrench supplied in the Kit, slacken the Needle Clamp Binding Screw (SL 1606E, P1.15) about half Turn the Handwheel to the position where the needle is descending but the Looper is still to the left. With the

Oil the needle at the Needle Guide before resuming work. under the point of the needle to press it against the stop whilst tightening the Clamp Binding Screw securely. that the butt end can be passed up through the Needle Guide into the Clamp until it contacts the Stop. There With the machine still in the same position, take the new needle and pass the point down through the Table so is no adjustment for the position of the Needle, which must always be fully home to the stop. Keep one finger

Switch off the machine. Removal and Replacement of the Awl.

Remove the Shield (VSM 518, Pl. 14).

in the casting above it, where the square socket wrench can be fitted on to it. Turn the machine to bring the Awl up so that the Awl Clamp Binding Screw (SL 290LF, P1.15) is under the recess

Slacken the Binding Screw and turn the machine to take the Awl down clear of the Table, when it can be withdrawn from the Clamp.

machine to bring the Awl up and hold it against the stop whilst tightening the Binding Screw securely. Leave the machine in this position to replace the Awl, which must be pushed fully home to its stop. Turn the

Setting of Spreader Point, (VSM 117, Pl.9). This is very important and is the first thing to check if thread breakage or missing of stitches occurs.

There is an eccentric adjustment at the rear end of the Spreader Lever Connecting Link, (VSM 44C, P1.9). This is normally set as in Fig.5 when viewed from the right side of the machine.

Needle Guide Lever (VSM 97B, P1.15) is vertical (Fig.6). With the machine in this position, the Spreader To obtain the correct setting of the Spreader Point, first turn the machine so that the front edge of the

Point should be almost touching the point of the Needle, very slightly to the left of it (Fig.7).

with the Spreader Point. The work must only be allowed to move along as the Awl feeds it. the operator, by moving the work as the needle draws the thread up from it, thus pulling the thread out of line be missed, but usually without breaking the thread. NOTE: The same effect can be the result of bad handling by the right, it may miss the loop altogether so that the shuttle will not pick up the thread and the stitch will which will break leaving a frayed piece about 4" (19mm) in length standing up from the sole. If set too far to point of the Shuttle passes cleanly through it. If set too far to the left, it will probably split the thread, At this setting, the Spreader Point should separate the loop of thread drawn up by the Needle, so that the

It should, however, rarely need adjustment once the correct setting has been made, The setting of the Spreader Point is very critical and only a very slight adjustment can make a great difference.

Set the Table so that the Awl just clears the back of the threat (Fig. 8). The Table is held by a taper cotter, (SDL 283E, Pl.14) and mut (NL 339E, Pl.14). Slacken the nut

a turn or so, and give it a sharp blow with a wooden mallet or similar to free the cotter. The table can then be moved in or out. Re-tighten the nut firmly after making the adjustment, but do not over-tighten.

Foot Release Lever to the desired position and re-tighten the nut. when the machine is in the starting position. To adjust, slacken the nut (NL 230E,P1.16), move the Presser 3/64" (lmm) between the Release Link Cam Roll, (RL 141E, Pl.16) and the back face of the Presser Foot Holder Presser Foot (VSM 90, Pl. 16). The Foot must be fully home (to the right) in the Holder and set approximately 1/16" (1.5mm) behind the needle. There must be a clearance of approximately

Setting of Looper, (VSM 91,P1.13) and Looper Hook, (VSM 07B,P1.13). fouling the barb (Fig. 9). If settoo high, its point may foul the underside of the Table (when fully to the left). The Looper must be set high enough to place the thread cleanly on to the needle without

piece of paper between it and the underside of the Table. When fully to the right, and forward, its point should or the Looper Hook when moving under it. When the Looper is fully to the left, it should be possible to pass a lie close to the left hand side of the needle, but not touching it (Fig.10).

The Looper Hook should be set so that it descends to the right of the thread held between the Table and the that it fouls the Looper. Looper and must come low enough to hold the thread securely when the Looper passes behind it, but not so low

therefore, only be determined by experience. The settings given above are for normal use, but may require <u>slight</u> modification to suit local conditions, as they are to some extent affected by the type of work, materials, and the handling of the operator, and can,

Depth of Lock, (Plate 3)

The importance of the correct setting for the depth of the lock cannot be over-emphasised. The term "lock"

result in the sole coming away from the welt after only a short period of wear. its function of holding the sole to the welt. As shown in the diagrams, the incorrect setting of the lock will means the point where the two threads cross, forming a "Knot" which can be likened to the head of a rivet in the sole to spring away. In Fig.1, the lock is too shallow; when the sole wears down to the level (A), the lock will be worn off, allowing

stitches. As soon as wear reaches (A) this thread will be worn through, and the sole will again spring away. In Fig. 2, the lock is too deep, and the sole is held on simply by the single strand of thread between the

undoubtedly be worn through. before the seam will part, by which time, (since this is at the edge of the sole), the centre of the sole will Fig. 3 shows the ideal position for the lock, firmly embedded in the substance of the sole. Wear must reach (A)

To adjust depth of lock

and well oiled; welt thread running freely through the waxpot and thread rolls; shuttle temperature correct. condition; bobbin freghly wound, with the correct amount of wax on the thread; shuttle and thread tension clean First ensure that all related factors are correct; i.e., both liquid and solid waxes are fresh and in good

material in use. Cut through this test piece vertically with a sharp knife so as to expose the stitching as Stitch together two pieces of leather, which ideally should be a strip of welting and a piece of the soling in Figs. 1, 2, or 3.

backwards away from the Operator. Only a very small amount of movement is required. the right-hand side of the machine head (see Fig. 4). First slacken the Binding Screw, (SL 1618E, P1.11), and, If this shows the lock to be incorrect, it may be adjusted by means of the small lever, (PL 2357, Pl.11), on if the lock has been too shallow (Fig.1) move the lever forward towards the Operator, or if too deep (Fig.2),

RETIGHTEN the Binding Screw, repeat the test and inspect, until the correct position is found.

should be required for a considerable period. Once set, the lock will be automatically adjusted to suit the thickness of the work, and no further attention

Awl Sharpening.

Hold the Awl securely, preferably in a proper Awl Filing Clamp, and rest it on the edge of a bench or the tray They may be carrefully finished on an oilstone, but an emery stick should not be used, as it leaves the bevels care to leave the corners quite sharp. The bevels should be quite flat from corner to corner, clean and smooth of the machine so that it is firm and cannot twist. Gut the bevels with a dead smooth file (WBAZ 206) taking rounded.

When viewed from the side (Fig.5), the inside corner (B) should be higher, so that it "leads" with this point. This angle (A) should not be overdone or the work will tend to be pushed off the machine.

It is important that the two bevels are as shown in the front view (Fig. 6). The outside bevel (C) must be

fairly short and steep and the inside bevel (D) long and shallow. This ensures that as the Awl penetrates the work the tendency for it to "spring" to the left is counteracted and full feed is obtained. This is particularly noticeable on a worn machine. Awis as supplied are generally of the correct shape and only require to be brought to a sharp edge.

General. brittle Use only freshly wound bobbins. If left standing for several days the wax will dry out and the thread become

Adjust the strippers on the waxpots (by tightening or slackening the two screws in the stripper plate) so that the thread is not too heavily waxed, as surplus wax caked round the shuttle etc. will interfere with the smooth Do not allow the hot waxpot to boil fiercely, or the wax will be spoilt. running of the thread and cause breakage.

work which tends to make the needle sticky.

Keep the machine clean and well oiled at all times. Keep the Needle Guide well oiled so that the spring can pull it easily down the needle, particularly on rubber

gather and the gravity of face supplies the strongs of the following as a face of the supplies of the supplies

OPERATI

Direction of Rotation:

top of the Handwheel moves towards the operator. The Handwheel rotates in an anti-clockwise direction, viewed from the right hand side of the machine, i.e., the

Preparation of work:

The sole may be attached to the shoe either by temporary nailing or by cementing. Cementing is recommended where the welts and/or insoles are very light and flexible. Any nails used must be well in from the edge of 3/64" (1mm) from the edge of the welt. Trimming too closely makes stitching more difficult due to lack of material for the Presser Foot to hold. this is not essential. The sole should be trimmed squarely and evenly with the welt, but not closer than free water remains. Rubber and synthetic materials will stitch more easily if the surface is wetted, although hard leather should be mellowed, i.e., thoroughly soaked in water and allowed to dry out partially, until no the sole, so as to be clear of the Presser Foot. Stitching may be in a channel, groove, slit or aloft.

operating:

electricity but spoils the wax. It will normally take approximately 20 minutes for the machine to reach working temperature, during which period it can be oiled (see Section 6) and a check made that the Thread Rolls are free to rotate. The shuttle is bot enough when the thread can be pulled easily from it by hand. Switch on the Heater Switch (2)(Pl.1). The Indicator Lamp (3) will glow to show that the current is on. Turn the Shuttle Simmerstat (4) to "Full". Check the amount of thread on the bobbin and, if this is not sufficient "Off" unless it is anticipated that bobbins will be required to be wound. Unnecessary heating not only wastes for the amount of work to be done, place a spare full bobbin on the Bobbin Holder over the Shuttle. A full bobbin normally holds sufficient for 8 pairs of mens' half soles. The Wax Pot Simmerstat (5) should remain at

Switch on the motor.

above the Table, and <u>rising</u>. Note that it will also appear to be in this position half a revolution earlier or later, when the needle is <u>descending</u>. Since the first action of the machine must be for the awl to rise and pierce the work in readiness for the passage of the needle on its downward stroke, it will be appreciated that to attempt reached and disengage the thread which will have been picked up by the barb of the needle. should start to move upward. If it moves downward, continue turning the Handwheel until the correct position is Check that the starting position is correct by pulling the top of the Handwheel forward slightly, when the needle to start in the wrong position will result in the needle breaking, as it will have no hole through which to pass. In order to commence stitching, the machine must be in the Starting Position, i.e., with the needle about 2"(13mm)

be disposed of by pulling out until it is felt to be wet again. The length of welt thread which runs from the Liquid Wax Pot through the Take-up etc. will have dried out and must

may be released by pulling forward the spring-loaded Thread Lock Hand Release Lever (VSM 193, Pl.11). If for any reason, it is required to pull the thread through with the machine in any other position, the lock This can only be done when the thread look is released, that is, when the machine is in the starting position.

Full out sufficient thread from the Shuttle so that both Shuttle thread and Welt thread can be held together under the spring clip of the Thread Holder (16,Pl.1).

the work, firmly but not too heavily. sole upward, toe to the right, with the welt resting on the top of the Table. Pull the Presser Foot down on to Raise the Presser Foot by pushing back the Presser Foot Raising Handle (8, Pl.1) and place the work on the machine,

of the Gauge by pressure of the work against it. If it should become too loose, this can be corrected by tightsite direction to the Edge Gauge. The Lever is deliberately made stiff to move, to prevent accidental movement welt can be pressed firmly against it and the stitches will lie in the centre of the welt and not drop down into The Edge Gauge (VSM 50, Pl.14) should be adjusted according to the width of the welt, so that the edge of the welt seam. The Edge Gauge is adjusted by means of the Edge Gauge Lever (7, 21.1), which moves in the oppo-

Do not stand centrally in front of the machine, but somewhat to the right-hand side, more in front of the Handwheel. The right foot should be well back, 24 - 30 inches (600 - 760 mm) from the machine. The left foot has the heel on In order to have full control over the machine and the work, it is important to adopt the proper operating position ening the Binding Screw (SL 1624E, Pl.14). tributed on both feet. It is a mistake to stand too closely to the machine, as this will not allow room to swing the floor and the ball of the foot on the Clutch Treadle, the left knee slightly bent and the weight evenly disthe shoe round when stitching round the toe; the heel will come against the operator's chest, making him lean

not moved during this time, as this would disalign the hole which the awl has just made and the needle would be when the work is held only by the Presser Foot and the operator's hands. It is most important that the work is There is a brief moment in the operating cycle, after the awl leaves the work and before the needle enters it, backwards just at the moment when it is most necessary to hold the work firmly on to the table and guide it round. back, or twist it. The function of the operator's hands is to hold the work into and down upon the Table, with the broken. Therefore, let the machine feed the work along in its own way; do not try to help it along, or hold it

running the looser part of the upper over the Table and accidentally stitching it. When approaching the waist on the finishing side, hold the heel down and well in to the machine; this will avoid sole as nearly level as possible.

drawing a loop of thread up through the work; stop just before the Spreader Point comes down and divides the loop. The finishing position is the same as the starting position, i.e., with the needle rising. The needle will be cutting off the thread close to the work. on the loop and making it easy to disengage it. Raise the Presser Foot and pull the work away from the machine, If the Handwheel is then moved very slightly backwards, the needle will come down a little, releasing the tension

721E, Pl.16) is removed. It will generally be found easier to stitch rubber and similar materials if one PresserFootSpring (SPGL

5

LUBRICATI

The Motor must be switched off whilst lubricating, use wH&B Machine Oil for all the points listed below:

Countershaft: During the first week's running, check the three oil cups daily, before starting up. less than half full. Subsequently, check weekly.

Access to the Countershaft is gained by removing the left-hand side panel. Turn the two fasteners at the top of the panel a quarter turn in either direction. Pull the panel away from the machine and up to remove it. To replace, turning it, until a click denotes that it is engaged. their original position and enter them into the holes in the Column. Press each fastener (not the panel) without first engage the two lugs at the lower end of the panel over the bar in the Column; turn the two fasteners back to

The Lubricator (VSM 473,Pl.7) provides a constant drip-feed to the Shuttle and should be kept between a quarter and three quarters full. To stop the flow open hinged part of cover.

Oil the needle frequently, particularly when stitching rubber or synthetic materials, which tend to make the Foot will jump when the awl strikes the work. If it becomes oily, it should be cleaned with paraffin. The sliding faces of the square part of the Presser Foot Holder (VSM 25, Pl.16) must NOT be oiled, otherwise the

when saturated with oil, act as wicks to maintain a controlled supply to the bearings and also keep out grit and working surfaces (e.g., cam rolls and gear segment teeth). Certain oil holes are fitted with felt plugs; these, All other moving parts should be ciled daily. Most have oil holes plainly visible; otherwise, apply oil to the

Do not overlook the oil hole for the Needle & Awl Segment, which is revealed by raising the Presser Foot.

Motor: with special grease by the manufacturers and this normally lasts the life of the motor. Although fitted with grease nipples, these should not be lubricated, except by a qualified engineer, as overlubrication or use of the wrong lubricant will seriously damage the motor. The bearings are packed

THE MACHINE MUST BE ISOLATED FROM THE MAINS ELECTRICITY SUPPLY BEFORE CARRYING OUT ANY MAINTENANCE WORK.

Belt Adjustment: Column, hold the Handwheel firmly to prevent it rotating and, with the motor running, apply pressure to the Clutch mine whether it is the motor belt or the machine head belt which is slipping, remove the left side panel from the ping; if it does, then the machine head belt is slipping. Treadle whilst watching the Countershaft pulley. If the pulley does not rotate, it is the motor belt which is slip-There will usually be some initial stretch with new belts, which will cause them to slip, indicated by the machine only running slowly despite full pressure on the Clutch Treadle. To deter-

Adjustment is effected by removing one or more links from the belt.

Slipping belts should be attended to promptly, otherwise the heat generated by the friction can melt out the lubricant from the countershaft bearings, ruin the belt and overheat the motor.

is to fit a new belt. Belt slip on an older machine is probably due to the belt having become saturated with oil, for which the only cure

Both liquid and hard wax pots should be cleaned out once a month, to remove sediment, which otherwise interferes with the free running and waxing of the thread.

underside of them. Check also the two thread Guide Screws, VSM 76F (P1.5) and replace these if the thread has worn a groove in the Before refilling the wax pots, check the condition of the rubber strippers, VSM 700, and replace if necessary.

tion", Section 6), this is due to wear on the face of the Presser Foot Holder, which can be adjusted as follows: After prolonged use, it may be found that the Presser Foot is inclined to jump when the awl strikes the work. Assuming that the Presser Foot Holder (VSM 25, Pl.16) is free from oil (see "Lubrica-

Slacken the nut, NL 341E (Pl.16). Test by raising the Presser Foot; it should move smoothly and with only sufficient freedom Turn the screw, SL 1616E (P1.16) very slightly in an anti-clockwise direction (viewed from the nut end). Keep the screwdriver in the slot in the screw to prevent it from rotating and tighten nut. to pull it down. Check the setting of the Release Link Cam Roll.

This must be replaced as soon as wear becomes apparent, otherwise a high rate of needle breakage

When fitting the new Guide, ensure that the face of the Lever is clean and that the Guide fits flush against it Needle Guide can then be carefully pulled off the two dowel pins in the Needle Guide Lever, VSM 97B (P1.15). To replace the Needle Guide, first remove the needle, then the Needle Guide Binding Screw, SL 797 (P1.15). the Binding Screw is tightened. The

When ordering a replacement Needle Guide, the size of the needle must always be quoted after the part number, e.g., "VSM 60E-45" (for a size 45 needle), or "VSM 60E-43" etc.

General: such parts as thread rolls, looper etc. and, in particular, the shuttle, as this will interfere with running of the thread, causing irregular stitching and frequent breakage. The machine should be kept clean and properly lubricated at all times. Do not allow wax to buid up on

excessively worn parts will rapidly damage other parts and lead to costly breakdowns.

Inspect the machine regularly for worn parts and do not delay their replacement. Running the machine with some

Velt thread breaks,

Indication

leaving a frayed end above the Below the work

Below the under the with fraying work.

work, without fraying. Looper a Service Engis

terisk(*), which rtain items in the "Remedy" column have been marked with an

with a great number of machines, Hopefully, you will not come up Whilst not claiming to be exhaustive, the list covers most of the faults which have been met with over many years experience than two or three of them; certainly, they can be

Fit new needle. Fit new parts.* Fit ne	Possible causes	Remedy	Indication	Pousible causes	Remedy
Spiriting the toried. Peter in wreadle. Reset. Lack of oil in shuttle. Lack of oil in shuttle. Lack incorrect pricking up on needle. Lack incorrectly girld. Reset. Re		-	- 1		'ncrease Simmerstat
Reset versely war in Looper Carn Excessive weer in Looper Carn Rolls. Excessive weer in Needle Suide. Excessive worr in Needle Suide. Fit new parts. Sugment Carrier Bush. And Fit new sorrevs. Table etc. Table et		Fit new needle.	not pulling		setting or allow more time for heating.
Excessive wear in Needle Suide. Take-up Thread Rolls size. Thread Guide Screws in Liquid Wax Fot. Take up Thread Rolls size. Thread Guide Screws in Liquid Wax Fot. Thread Guide Screws in Needle & Awd Cheek and re-adjust took. The sept. Thread Guide Screws in Needle & Awd Cheek and re-adjust or galgas with stringernery, or fire oil-stone. Thread Guide Screws in Needle & Awd Excessive waar in Needle & Awd Segment Carrier Bush. The thread Guide Screws in Needle & Awd Expessive war in Needle & Awd Segment Carrier Bush. The consider worn on Shuttle, The sept. The sept. Thread Guide Screws in Needle & Awd Expessive war in Needle & Awd Segment Carrier Bush. The consider worn on Shuttle, The sept. Thread Guide Screws in Needle & Awd Expessive war in Needle & Awd Segment Carrier Bush. The trew screws. Thread Guide Screws in Needle & Awd Expessive war in Needle & Awd Segment Carrier Bush. The consider worn on Shuttle, The sept. Thread Guide Screws in Needle & Awd Expessive war in Needle & Awd Segment Carrier Bush. The wax constituted. Thread Guide Screws in Needle & Awd Expessive war in Needle & Awd Misplaced Table (too for back (needle runs into well samh). Expessive war in Needle & Awd Misplaced Table (too for back (needle runs into well samh). Edge Guage sat too fire back. Edge Guage sat too fire with needle) Misplaced Table (too for worn (work held cheedle runs into well samh). Edge Guage sat too fire worn (work held cheedle runs into well samh). Edge Guage sat too fire worn (work held cheedle runs into well samh). Edge Guage sat too		Re-set. Fit new Looper.			Lubricate. Increase setting.
Roissie waar in Needle S. Awi Segment Carrier Bush Insufficient wax on thread. Take-up Tread and les sized. Use of incorrect thread. Use of incorrect thread. Use of incorrect thread. Staps edges worn on Shuttle, Sharp edges worn on Shuttle, Sharp edges worn on Shuttle, Staps edges worn on Shuttle, Sharp e		Fit new parts.*		Worn needle guide.	Fit new guide.
insufficient wax on thread. Check contents of wax frake-up Thread Rolls seized. Groove worn in underside of Thread Rolls seized. Groove worn in Underside of Thread Guide Screws in Liquid Wax Pot. Bethread. Lex clin incorrectly threaded. Lex dide Screws in Liquid Wax Pot. Sharp edges worn on Shuttle, Sharp edges worn on Shuttle, Table etc. Table table, table to out of line with needle at anyle to Table (to far floward) Table table, table to out of line with needle at anyle to Table (to far floward) Table etc. Tab		Fit new Guide. Fit new parts.*			check Needle Guide . Spring and replace if stretched or broken.
Groove vorm in inderside of Thread Groove vorm in inderside of Thread Groove vorm in inderside of Thread Groove in Liquid Machine incorrectly threaded. Machine incorrectly threaded. Lex of incorrect thread. Lex of incorrect thread. Sharp edges worn on Shuttle, Sharp edges worn on Shuttle, Sharp edges worn on Shuttle, Table etc.		Check contents of wax pot; adjust stripper. Dismantle and clean.	3 1	Misplaced Table (too far back). Excessive wear in Needle & Awl	Re-set. Fit new parts.*
Machine incorrectly threaded. Use of incorrect threade. Excassive lock. Sharp adges worn on Shuttle, Sharp adges worn on Shuttle, Table at Carles Back and forth own Table at Carles Back and Table too far froward) Table too for forward) Table too for forward) Table too far forward and table too for and table too for table too forward. Table at Carles Back and forth own Table at Carles Back and Tabl		Fit new screws.		Segment Carrier busit. Edge Gauge set too far back (needle runs into welt seam).	Re-adjust. Tighten screw on clamp if Gauge can be pushed back.
Table etc. Labels and forth over supported parts. Remove adgrey with string-emery, or fine oil-stone. Re-etc. Re-etc. Re-etc. Re-etc. Fit new Spreader Point. Fit ne	C	Re-thread. Change to correct thread. Check and re-adjust lock. Test by drawing thread		Edge Gauge bent or worn (work held at angle to Table). Awl bent (hole out of line with needle)	Fit new Edge Gauge. Fit new awl.
Fit new Spreader Point. Fit new parts.* Check and re-adjust or replace. Replace bobbin with reselvition would one. (Strip of and scrap solidabin for adjustion transport of the reselvition of the re		back and forth over suspected parts. Remove edges with string-emery, or fine oil-stone.	Barb repeatedly broken off needle (needle rising).	Worn awl (making hole too small) Misplaced Table (too far forward) Misplaced Presser Foot (too far forward).	Fit new awl. Re-set. Re-set.
oper Hook. Check and readjust or replace. Fit new needle. Fit new needle. Replace bodbin with fresh wound one. (Strip heat of speed.) Fit new needle. Replace bodbin with fresh was not speed. Fit new needle. Replace bodbin with fresh was not speed. Joss of speed. Belt slip. Belt slip. Belt slip. Bottruction (e.g., leather outting) on frozen sheat only when required for winding. Bropty was not said refill with fresh was. Heat only when required for winding. Strip of freed destand	Spreader Point set too far right. Spreader Point worn. Excessive wear in Needle & Awl Segment Carrier Bush.	Re-set. Fit new Spreader Point. Fit new parts.*	Presser Foot jumping	Oil on faces of Presser Foot Holder. Presser Foot Holder worn. Release Link wrongly set (cam roll	Clean with paraffin Adjust. Re-set.
heart freshy wound one. Strip teath freshy wound one. Strip of thread). Remove bobbin with thread). Remove bobbin from heart down, when machine is lengthy waspot and refull by when required for winding. Strip of find diseared in the strip of the strip	Worn or misplaced Looper Hook. Barb broken off needle.	replace. Fit new needle.	Loss of feed action		Re-sharpen.
down, when machine is Soles springing Lock incorrect (probably too deep). Empty waxpot and refill away in wear. with fresh wax. Heat only when required for winding. Strip of frad discard	Wax dried out through being left too long at full shuttle heat between operating periods.	Replace bobbin with freshly wound one. (Strip off and scrap spoiled thread). Remove bobbin from shuffle of the heat	Loss of speed.	Belt slip. Obstruction (e.g., leather cutting) on floor under treadle.	Tighten belt(s) Rake clear
	Wax in hard pot spoiled by excessive or prolonged heating. Badly wound bobbin allowing	down, when machine is idle. Empty waxpot and refill with fresh wax. Heat only when required for winding. Strip off and discard thread; rewind evenly.	Soles springing away in wear.	Lock incorrect (probably too deep).	Check shuttle heat and free running of threads. If in order, check and readjust lock.

Shuttle thread breaks.

thread to become tangled.

Stitches missed.